

From: [Owens, Robert](#)
To: [Mueller, Brian](#)
Subject: Falcon Refinery RI/FS (TO088) - DESR Figures and Tables (Email 4)
Date: Friday, July 11, 2014 8:28:02 AM
Attachments: [Figure 6 AOC4.pdf](#)
[Figure 5 AOC3.pdf](#)
[Figure 7 AOC5.pdf](#)

Brian:

Attached are more working copy tables and figures from the Falcon DESR. The highlighted items are attached to this email. Let me know if you have problems receiving the items.

Thank you,
Bob Owens
EA Engineering, Science, and Technology, Inc.
405 S. Highway 121, Building C, Suite 100
Lewisville, TX 75067
972-315-3922 ext 1210
Direct: 972-538-2701
Mobile: 972-989-7956
Fax: 972-315-5181

List of Tables and Figures (Highlighted Items are Attached to This Email)

Table A-1 Surface Soil Data Summary – 0 to 0.5 Feet below Ground Surface
Table A-2 Subsurface Soil Data Summary – Greater than 0.5 Feet below Ground Surface
Table A-3 Ground Water Data Summary
Table A-4 Sediment Data Summary
Table A-5 Surface Water Data Summary
Table A-6 Surface Soil Data Comparison to EPA Screening Levels – 0 to 0.5 Feet below Ground Surface
Table A-7 Surface Soil Data Comparison to State Screening Levels – 0 to 0.5 Feet below Ground Surface
Table A-7 Subsurface Soil Data Analyses – Greater than 0.5 Feet below Ground Surface
Table A-8 Ground Water Data Analyses
Table A-9 Sediment Data Analyses
Table A-10 Surface Water Data Analyses
Table F-1 Field Duplicate Relative Percent Difference Calculations
Table F-2 Rejected Analytical Results (R Qualifier)
Figure 1 – Site Map
Figure 2 – Sample Location Map for Area of Concern 1N
Figure 3 – Sample Location Map for Area of Concern 1S
Figure 4 – Sample Location Map for Area of Concern 2
Figure 5 – Sample Location Map for Area of Concern 3
Figure 6 - Sample Location Map for Area of Concern 4
Figure 7 - Sample Location Map for Area of Concern 5
Figure 8 – Sample Location Map for Area of Concern 6
Figure 9 – Sample Location Map for Area of Concern 7
Figure 10 - Sample Location Map for Background Samples



9560893